Inspection Field-crop sprayers

All Field-crop sprayers are inspected according to regulations of the Product Board for Agriculture and Horticulture.

A nation wide network of SKL certified testing stations performs the inspections.

What is inspected:



STICHTING KWALITEITSEISEN LANDBOUWTECHNIEK (SKL) te WAGENINGEN

KEURINGSFORMULIER VELDSPUITEN

Results inspections 2006



Most occurring failures:	
1	Leakages / dripping nozzles
2	Distribution spray nozzles
3	Lacks concerning the spray boom
4	Bended or damaged hoses
5	Bad readability of the content of the liquid tank

Number of inspected field crop sprayers